

- Continuous ground monitor for single operator
- Ideal for workstation and/or field service use
- Compact size
- Alarm indicates:
 - Ground disconnection
 - Low battery
 - High resistance wrist strap
- Improved grounding clip
- Auto switch on/off
- Parking snap stand-by feature
- PP3 battery required, Order Code 908-526



STA99

	Mfrs. List No.	Order Code	Price Each		
			1+	10+	50+
Wrist Strap Monitor	725	162-772†			
Dual Conductor Wrist Strap	2368	996-944†			
Dual Conductor Ground Cord	2360	996-956†			
Belt Clip	723	996-993†			
Standard Calibration Charge			S	Each	☎

† Available until stocks are exhausted

Wrist Strap Test Point



H = 178, W = 305

- Wall mounted
- Quick and easy to use
- Clear instructions displayed on the back plate
- Comprises wrist strap checker, earth reference point, back plate and 77mm patch cord



- Green LED and audible tone indicates 'Pass'
- 'Hi-fail' yellow LED indication if >35M ohms
- 'Low fail' red LED indication if <900k ohms
- Accepts 4mm/10mm press-studs and banana plugs
- Conforms to **EN 100 015-1**

STA62

	Mfrs. List No.	Order Code	Price Each		
			1+	3+	10+
	23-9818	179-243			
Standard Calibration Charge			S	Each	☎

Wrist Strap Test Station



Wrist Strap Tester H = 145, W = 90, D = 34
Wall Panel H = 300, W = 600

Mfrs. List No.
H221 = 595-925, H201 = 595-937.



- Test station includes tester and wall panel
- "Pass" LED and buzzer
- "High-Fail", "Low-Fail" and "Low battery" LEDs
- Sockets for 4mm shrouded plug, 4mm and 10mm press socket
- Wrist strap tester available separately
- 9V PP3 battery required, Order Code 908-526
- Conforms to **IEC 61340-5-1**

STA63

	Order Code	Price Each		
		1+	5+	20+
Wrist Strap Test Station	595-925			
Wrist Strap Tester only	595-937			
Uncalibrated				
Standard Calibration Charge		S	Each	☎

Personnel Test Stand



- Tests wriststrap and footwear
- Tests to **IEC 61340-5-1**
- Pass range is 0.1 to 35MΩ for footwear, and 0.75 to 35MΩ for wriststrap
- Weight 8kg

This test stand is a free standing test station. It is flat-packed and can be put together in a few minutes. Supplied with footwear tester, H203. Its robust construction makes it suitable for large facilities.

STA123

	Mfrs. List No.	Order Code	Price Each		
			1+	5+	10+
	H2023	302-6796			
Standard Calibration Charge			S	Each	☎

Footwear Test Station



Footwear Tester: H = 145, W = 90, D = 34
Wall Panel: H = 300, W = 600
Test Mat: W = 390, D = 360



- Combined test unit, wall panel and test mat
- Checks conductive shoes, heel and toe grounders
- "High-Fail", "Low-Fail" and "Low battery" LEDs
- LED and buzzer indicate "pass"
- 20V (open circuit) test voltage
- 9V PP3 battery required, Order Code 908-526
- Conforms to **IEC 61340-5-1**

STA64

	Mfrs. List No.	Order Code	Price Each		
			1+	5+	20+
	H223	595-950			
Standard Calibration Charge			S	Each	☎

Wrist Strap Auditing Tester



The concept of this auditing system is to test the wrist straps without disconnecting them from their grounding point, hence testing the whole grounding circuit rather than just the wrist strap itself, as it would be done with a conventional tester.

- Checks UK 13 Amp mains socket for good earth and correct wiring
- Can be used for footwear verification
- Ideal for an ESD co-ordinator or auditor
- Pass range: 0.75 to 35MΩ ±6%
- Red LED indicates fail, green LED and buzzer indicate pass

- Function test button
- Main lead is 1 metre long

STA120

	Mfrs. List No.	Order Code	Price Each		
			1+	5+	10+
Mains Plug	H520	302-6930			
Schuko Euro Plug	H520EU	322-4788			
Standard Calibration Charge			S	Each	☎

continued