

## PFA Insulated Screened Copper Cable for Use with PRT Sensors

:



- Core colours red + white
- 4 core & 6 core 7/0.2 PFA/screened /PFA Insulated
- Copper cable for use with Platinum Resistance Thermometers & most process signals
- Insulation Temperature Rating: 260°C

| Length/Cores | FARNELL code | Labfacility code | Lab Data Code | Lab Stock Code |
|--------------|--------------|------------------|---------------|----------------|
| 10m 4 core   | TBA          | WC-052 x10       | FAR61/B       | XF-522-D       |
| 25m 4 core   | TBA          | WC-052 x25       | FAR61/C       | XF-523-D       |
| 10m 6 core   | TBA          | WC-062 x10       | FAR61/D       | XF-524-D       |
| 25m 6 core   | TBA          | WC-062x25        | FAR61/E       | XF-525-D       |

Data Ref: FAR61B-E