

# CABLE ASSEMBLY INSTRUCTIONS


NUT




WASHER




MAIN BODY




CONTACT PIN FERRULE




STEP 1




STEP 2



STEP 3



STEP 4



DESCRIPTION

MMCX Jack Str. B'head Crimp  
for Cable type RG174U

TOLERANCE

DRAWING NO.

429-7283

UNIT

mm

SCALE

2:1

REV.

A-0

.X ± 0.5

.XX ± 0.3