

De las tabeli tehnicele sunt
 pentru detalii
 referitoare la
 dimensiuni si
 materiale



Part Name	QTY	Part No.	Part No.	Part No.
(1)	6	4100-3193	4101-1416	4102
(2)	30	4100-0152	4101-1417	4103
(3)	18	4100-0112	4101-1418	4104
(4)	30	4100-0111	4101-1419	4105
(5)	30	4100-0110	4101-1420	4106
(6)	30	4100-0109	4101-1421	4107
(7)	30	4100-0108	4101-1422	4108
(8)	30	4100-0107	4101-1423	4109
(9)	30	4100-0106	4101-1424	4110
(10)	30	4100-0105	4101-1425	4111
(11)	30	4100-0104	4101-1426	4112
(12)	30	4100-0103	4101-1427	4113
(13)	30	4100-0102	4101-1428	4114
(14)	30	4100-0101	4101-1429	4115
(15)	30	4100-0100	4101-1430	4116

Dimensiunile sunt date in milimetri
 si sunt valabile pentru toate
 dimensiunile de fabricatie


Dimensiunile liberate sunt
 indicate in tabelul
 aditional general, indicate in
 tabelul liberat, indicate in
 tabelul liberat si in tabelul
 liberat

LASERMARKING SE RITN: 4100-4648
 LASERMARKING SEE DIMS: 4100-4648

Qty	Part/Description	Part No.	Rev
7	4101-1416, 4101-1417 - 2x 4100-0731A (AU 0101271)	010712	FRMA




* 4100-3693, 4100-0152, 4100-0116, 4101-0014, D
 PACKS SEPARAT I PLASTICASE 4100-0479 DEH LAGGS I FORPACKNING
 PACED SEPARATY I N PLASTIC GAGS 4100-0479 AND SUPPLED IN BOX



4100-0479
 4100-0016
 4100-0522
 4100-3693
 4101-0014(D)

FIBRESPANNING / PRELOAD : 180±20 N
 KRIMP-HÖHDE / CRIMP HEIGHT 18-20 166±0.05
 22-26 154±0.05

152-002



Material	Part No.	Part No.	Part No.	Part No.	Part No.	Part No.	Part No.
4100-0479	4100-0016	4100-0522	4100-3693	4101-0014(D)	4100-2673	4100-3776	4101-1416

Part No.	Part No.	Part No.	Part No.	Part No.	Part No.	Part No.	Part No.
4100-0479	4100-0016	4100-0522	4100-3693	4101-0014(D)	4100-2673	4100-3776	4101-1416

Part No.	Part No.	Part No.	Part No.	Part No.	Part No.	Part No.	Part No.
4100-0479	4100-0016	4100-0522	4100-3693	4101-0014(D)	4100-2673	4100-3776	4101-1416