


Volume Extraction **Accessories**

Accessories for volume extraction

Description Order No.




Extraction arm WFAF 50 50 mm dia flexible extraction arm with 100 mm dia funnel, for use with WFFMP 50 system seal. ESD safe. Max. length 840 mm.



005 36 372 99




Extraction arm WFAS 50 50 mm dia flexible extraction arm with 210 x 20 mm flat nozzle, for use with WFFMP 50 system seal. ESD safe. Max. length 820 mm.



005 36 373 99



Exhaust hood WFCC 50 240 x 100 mm with flexible hose 1m long, recommended for use with hot air soldering operations, for use with WFFMP 50 system seal. ESD safe.





Exhaust hood, 200 x 100 mm recommended for use with hot air soldering operations uses extraction hose 50.

005 87 358 45



Accessories for volume extraction

Description Order no.



Extraction plate WFDD 50 300 x 210 mm with 1m flexible hose, for adhesive and solvent fume extraction. Uses system seal WFFMP 50. ESD safe.

005 36 370 99

005 36 380 99



Extraction bench 40 effective working area 600 x 350 mm, for adhesive and solvent fume extraction. Hose connections from side or below. Check hose size info quotes extraction hose 40 and adapter 40-50 neither of which are listed.



System seal WFFMP 50 can be mounted directly to work bench or to mounting bracket.

It has a spring loaded cover to physically seal the system if an accessory is withdrawn. Connects to hose 50. ESD safe.

005 36 371 99





Bench mounting bracket WFTB 50 for WFFMP 50. Metal, black.



005 36 379 99