Steel Rules

Metric



Two sides - four edges. Subdivided mm, $\frac{1}{2}$ mm, figured every 10mm one side, subdivided mm figured every 10mm in mm other side reading left to right bottom edge and left to right top edge when inverted. Square ends. Rustless. FR patterns are flexible.