
Industry





CAL Adjusting program (CAL): For quick setting of the balance's accuracy. External adjusting weight required.

Weighing units: can be switched to e.g. non-metric units at the UNIT to e.g. non-method a key. See balance model

Animal weighing program: strong vibrations are filtered out.


TAR Tare: put back displayed value to "0" during weighing process, e.g. 0.00 to add or remove weighing material from a container.



HDB•CH

Hanging scale





KERN & SOHN GmbH – Balances, Weights, DKD Calibration Laboratory • Ziegelei 1 • 72336 Balingen-Frommern • Tel.: + 49-7433-9933-0 • info@kern-sohn.com • www.kern-sohn.com

from 1 mg up to 2000 kg DKD = German Calibration **S**ervice